

## Category L2 → 1 Alarm Upgrade

Company/ System	Evaluation No:	Feature Code	Fitment Policy	Years	Standard Option/ Retrofit W/Wide
<b>Autowatch</b> 375 Clam LCV	TUL1 – 116/0704	R U L	Universal with Category L2		
<b>Autowatch</b> 458 RL LCV	TUL1 – 148/0807	R U L	Universal with Category L2		
<b>Autowatch</b> 695 RLC	TUL3 – 156/1108	R 2 U L	Universal with Category L2		
<b>Cobra</b> 4198 LCV	TUL1 – 127/0606	R U L	Universal with Category L2		
<b>Cobra</b> 4405 LCV	TUL3 – 161/1208	R U L	Universal with Category L2		
<b>Cobra</b> 4425 LCV	TUL3 – 162/1208	R U L	Universal with Category L2		
<b>Cobra</b> 4485 LCV	TUL3 – 163/1208	R U L	Universal with Category L2		
<b>Cobra</b> 8168/6	TUL1 – 69/1001	R U/M L	Universal with Category L2		
<b>Gemini</b> 7621T LCV	TUL1 – 128/1005	R U L	Universal with Category L2		
<b>Gemini</b> 7590T LCV	TUL1 – 129/1105	R U L	Universal with Category L2		
<b>*Hornet</b> Maxx 221 LCV	TUL3 – 173/1211	R U L	Universal with Category L2		
<b>Laserline (S.p.A)</b> 212 LCV	TUL1 – 134/0506	R U/M L E O	Universal with Category L2		
<b>Laserline (S.p.A)</b> 290 i2 LCV	TUL1 – 45/1200	R U/M L E O	Universal with Category L2		
<b>LDV Ltd</b> Vanshield BD 121	TUL1 – 59/0301	R U L	Pilot Convoy	98 – on 98 – on	O O
<b>Metasystem</b> EasyScan C/A Alarm LCV	TUL3 – 165/1009	R U L	Universal with Category L2		
<b>Metasystem</b> HPAT 5.0	TUL1 – 109/0304	R U L	Universal with Category L2		
<b>Renault</b> Goldshield II	TUL1 – 19/0798	R/ K U L	Kangoo New Master	Jun 98 – on	O/R
<b>Renault</b> Premier Alarm	TUL1 – 20/0898	R M L	Kangoo New Master	Jun 98 – 99 Jun 98 – 99	O/R O/R
<b>Renault</b> Premier Alarm 8268 LCV	TUL1 – 42/0800	R U L	Kangoo New Master	Jun 99 – on Jun 99 – on	O/R O/R
<b>Renault</b> Compact Alarm 7887 LCV	TUL1 – 132/0206	R 2 L	Kangoo	98 – on	O
<b>Sigma</b> S34 LCV	TUL1 – 106/0304	R/K U L E O	Universal with Category L2		
<b>Vauxhall</b> Security System MVX1 LCV	TUL1 – 110/0304	R U L	Universal with Category L2		

\* For Helpline Contact Information see Direct Electronics

## THE LISTING OF SYSTEMS DELETED FROM LIST [AFTERMARKET]

CAT L2 → 1 Alarm Upgrade				
<b>Autowatch</b>	161 RL LCV	Universal with CAT L2	TUL1 – 29/1099	January 2012
<b>Avital</b>	Maxx 2 LCV	Universal with CAT L2	TUL1 – 77/0402	December 2006
<b>Cobra</b>	6402	Universal with CAT L2	TUL1 – 18/0198	August 2007
<b>Cobra</b>	7908/18	Universal with CAT L2	TUL1 – 70/1001	August 2007
<b>Cobra</b>	3198 LCV	Universal with CAT L2	TUL1 – 79/0402	January 2012
<b>Gemel</b>	GR470 LCV	Universal with CAT L2	TUL1 – 25/0499	December 2006
<b>Hamilton &amp; Palmer</b>	Black Box LCV 2-1	Universal with CAT L2	TUL1 – 82/0802	November 2009
<b>Laserline</b>	290i LCV	Universal with CAT L2	TUL1 – 28/0499	March 2004
<b>Meta</b>	M99 T	Universal with CAT L2	TUL1 – 21/0898	April 2008
<b>Meta</b>	M99 T (Microwave)	Universal with CAT L2	TUL1 – 22/0898	April 2008
<b>Scorpion</b>	1012 T2 LCV	Universal with CAT L2	TUL1 – 36/0300	August 2010
<b>Scorpion</b>	1015 T2 LCV	Universal with CAT L2	TUL1 – 26/0499	August 2010
<b>Scorpion</b>	1215 T LCV	Universal with CAT L2	TUL1 – 92/0403	August 2010

<b>Scorpion</b>	SA70 LCV	Universal with CAT L2	TUL1 – 141/1106	August 2010
<b>Scorpion</b>	SA80 LCV	Universal with CAT L2	TUL1 – 142/1106	August 2010
<b>Secure Microsystems</b>	Sigma M34 LCV	Universal with CAT L2	TUL1 – 48/0101	December 2006
<b>Toad</b>	Compact C4 LCV	Universal with CAT L2	TUL1 – 52/0101	August 2010
<b>Van Bitz</b>	Strikeback T	Universal with CAT L2	TUL1 – 1270/1202	March 2010

These systems should be recognised as normal compliant systems **if installed prior** to the date of deletion shown unless otherwise indicated. These systems may no longer be in production and may have been superseded by an updated system.

Please note the above statement is subject to individual insurer's discretion.

## Category L2 → 1

### [Utilising the original equipment remote tested to Issue 2 Criteria]

Company/System	Evaluation No	Feature Code	Applicable Vehicles
<b>Autowatch</b> 375 LCV	TUL1 – 116/0704	R U L	<b>For applicable vehicles with an approved remote. Please contact manufacturer for fitment compatibility.</b>
<b>Autowatch</b> 695 RLC CAN	TUL3 – 157/1108	R 2 U L	
<b>Clifford</b> 330 X1/ X2/ X3 LCV	TUL3 – 153/0308	R U L	
<b>Cobra</b> 3868 LCV	TUL1 – 91/0403	R U L	
<b>Cobra</b> 4908 LCV	TUL1 – 137/0606	R U L	
<b>Gemini</b> 931T LCV	TUL3 – 167/1210	R U L	
<b>Laserline (S.p.A.)</b> 270 UK LCV	TUL1 – 75/0302	R U/M L E O	
<b>Laserline (S.p.A.)</b> 278 LCV	TUL1 – 135/0506	R U/M L E O	
<b>Laserline (S.p.A.)</b> 670 LCV	TUL1 – 1511207	R U/M L E O	
<b>*MED (S.p.A.)</b> 7450UK LCV	TUL3 – 166/0310	R U L	
<b>Sigma</b> S32 LCV	TUL3 – 169/0111	R/K U L E O	<b>Ford, Toyota, Mazda, BMW, Mercedes Benz, Fiat</b>
<b>Sigma</b> S35 LCV	TUL3 – 172/1111	R U L	
<b>Vauxhall</b> Security System MVX2/3 LCV	TUL1 – 111/0304	R U L	
			<b>Vauxhall models without CAN BUS</b>

\*See Landi Renzo S.p.A.

## THE LISTING OF SYSTEMS DELETED FROM LIST [AFTERMARKET]

CAT L2 → 1 Alarm Upgrade (Utilising the original equipment remote)				
<b>Clifford</b>	330 X2 LCV	Universal with CAT L2	TUL3 – 154/0308	March 2010
<b>Clifford</b>	330 X3 LCV	Universal with CAT L2	TUL3 – 155/0308	March 2010
<b>Metasystems</b>	HPB T LCV	Universal with CAT L2	TUL1 – 108/0304	December 2010
<b>Scorpion</b>	SA40 LCV	Universal with CAT L2	TUL1 – 1140/1106	December 2010
<b>Secure Microsystems</b>	Sigma M32 LCV	Universal with CAT L2	TUL1 – 47/0101	December 2006
<b>Sigma</b>	S32 LCV	Universal with CAT L2	TUL1 – 105/0304	January 2012
<b>Toad</b>	A850 T2 LCV	Universal with CAT L2	TUL1 – 67/0801	August 2010
<b>Vauxhall</b>	Security System MVX3 LCV	Universal with CAT L2	TUL1 – 1318/0404	January 2010
<b>Van Bitz</b>	Strikeback CAN Alarm	Universal with CAT L2	TUL1 – 143/0607	April 2010

These systems should be recognised as normal compliant systems **if installed prior** to the date of deletion shown unless otherwise indicated. These systems may no longer be in production and may have been superseded by an updated system.

Please note the above statement is subject to individual insurer's discretion.