

# PASSENGER CARS

## Category 2 → 1 (ORIGINAL EQUIPMENT SYSTEMS) Alarm Upgrade

Company/ System	Evaluation No:	Feature Code	Fitment Policy	Years	Standard Option/ Retrofit W/Wide
<b>Citroën</b> 9471 AW 9471 H5	TU2 – 1121/0401	R U L	Citroën C5 C3	All Apr 02 – on	O/R O/R
<b>Citroën</b> 9471 AY <i>(Part No 9471 G1 from Jan 01)</i>	TU2 – 1148/0400	R U L	All models with Cat 2 OE approved immobilisers and RF RKE systems	All	O/R
<b>Citroën</b> 9471 C1 <i>(Part No 9471 G2 from Jan 01)</i>	TU2 – 1147/0400	R U L	All models with an approved Cat 2 immobiliser	All	O/R
<b>Citroën</b> 9471.K3	TU2 – 1288/0403	R U L	Berlingo Picasso	Jan 03 – on Jan 03 – on	R R
<b>Ford</b> MFD1 by Metasystem	TU2 – 1388/1206	R U L	C-Max Focus Fiesta Fusion	Mar 03 – on Jul 04 – on Jan 07 – on Jan 07 – on	O/R O/R O/R O/R
<b>Hyundai</b> Approved 2-1 Alarm	TU2 – 1351/0705	R U L	Hyundai Coupe	Aug 05 – on	O/R
<b>MINI</b> DWA/EWS 2-1	TU2 – 1384/1006	R U L	All Models	Sept 03 – on	O/R
<b>Peugeot</b> 9671.ZK	TU2 – 1206/0301	R U L	Peugeot Models with O.E RKE Peugeot 406 with O.E RKE without deadlocks	All Apr 03 – on	O/R O/R
<b>Peugeot</b> 9671.ZL	TU2 – 1207/0301	R U L	All Peugeot Models	All	O
<b>Peugeot</b> 96731 R	TU2 – 1055/1098	R L O U	Peugeot Models	All	O/R
<b>Peugeot</b> 96731 V	TU2 – 1098/0699	R U L	Peugeot 206 406 605 806	All 99 MY with keypad All All	O/R O/R O/R O/R
<b>Peugeot</b> PSA sub-B Alarm	TU2 – 1349/0705	R U L	Peugeot 107	Jun 05 – on	O
<b>Porsche</b> PA 2000 Upgrade	TU2 – 1113/0899	R U L E	All Porsche Cars	All	O/R
<b>Renault</b> Goldshield II	TU2 – 806/0198	R/ K U L	Clio Phase 3 Clio 98 Megane (all models except Cabriolet) Laguna Safrane	Aug 98 – on Aug 98 – on Aug 98 – on Aug 98 – on Aug 98 – on	O/R O/R O/R O/R O/R
<b>Seat</b> Compact Alarm	TU2 – 1107/0899	R S U L M	Toledo	May 99 – on	O/R
<b>Seat</b> Ibiza 1400 T2	TU2 – 1271/1002	R U L	Ibiza	May 02 – on	O
<b>Skoda</b> VAG 1400 T2	TU2 – 1215/0401	R U L	Fabia	All	O/R
<b>Skoda</b> 1400 T2	TU2 – 1262/0802	R U L	Octavia	Jun 98 – on	O
<b>Toyota</b> PZ464-00130-00	TU2 – 1381/0107	R U L	Avensis Corolla Sedan Yaris Rav-4	Feb 07 – on Feb 07 – on Feb 07 – on Feb 07 – on	O O O O
<b>VAG</b> 1315 T2	TU2 – 1173/0800	R U L	VAG Models	All	O/R
<b>Vauxhall</b> Security System MVX1	TU2 – 1315/0304	R U L	All models except Can Bus	All	O/R
<b>Volkswagen</b> Beetle Alarm Upgrade	TU2 – 1231/1001	R U L	All Models	All	O/R
<b>Volkswagen</b> Polo 1400 T2	TU2 – 1244/0102	R U L	Polo All Models	Jan 02 – on	O

## Category 2 → 1 (AFTERMARKET SYSTEMS) Alarm Upgrade

Company/ System	Evaluation No	Feature Code	Fitment Policy
<b>Autowatch</b> 375 Clam	TU2 – 1313/0504	R U L E	Universal with Category 2
<b>Autowatch</b> 458 RL	TU2 – 1405/0807	R U L	Universal with Category 2
<b>Autowatch</b> 695 RLC	TU3 – 1447/1108	R 2 U L	Universal with Category 2
<b>Cobra</b> 3998	TU2 – 1257/1202	R U L	Universal with Category 2
<b>Cobra</b> 4198	TU2 – 1356/0606	R U L	Universal with Category 2
<b>Cobra</b> G198	TU2 – 1413/0907	R U L	Universal with Category 2
<b>Cobra</b> 4425	TU3 – 1451/1208	R U L	Universal with Category 2
<b>Cobra</b> 4485	TU3 – 1452/1208	R U L	Universal with Category 2
<b>Gemini</b> 7590T	TU2 – 1316/1105	R U L	Universal with Category 2
<b>*Hornet</b> Maxx 221	TU2 – 1394/1206	R 2 U L	Universal with Category 2
<b>Laserline (S.p.A)</b> 212	TU2 – 1368/0506	R U/M L E O	Universal with Category 2
<b>Laserline (S.p.A)</b> 290 i2	TU2 – 1183/1100	R U/M L E O	Universal with Category 2
<b>Metasystem</b> HPA/ T	TU2 – 1305/0304	R U L	Universal with Category 2
<b>Metasystem</b> Easycan C/A Alarm	TU3 – 1468/1009	R U L	Universal with Category 2
<b>*Sigma</b> S34	TU2 – 1301/0204	R/K U L E O	Universal with Category 2

\*For Helpline Contact Information see Toad

\* For Helpline Contact Information see Direct Electronics

## THE LISTING OF SYSTEMS DELETED FROM LIST [AFTERMARKET]

CAT 2 → 1 SYSTEMS				
<b>Autowatch</b>	161 RL	Universal	TU2 – 908/0198	January 2012
<b>CEL</b>	Topline 4001	Universal	TU1 – 279/1295	28 Feb 1998
<b>CEL</b>	Topline 5001	Universal	TU1 – 267/1295	28 Feb 1998
<b>Clifford</b>	Avital Maxx 2	Universal	TU2 – 1252/0402	December 2006
<b>Cobra</b>	6402	Universal	TU2 – 399/0597	May 2003
<b>Cobra</b>	7908/18	Universal	TU2 – 1007/0798	May 2003
<b>Cobra</b>	886	Universal	TU1 – 308/0496	October 1998
<b>Cobra</b>	7518/15	Universal	TU2 – 1238/1101	August 2007
<b>Cobra</b>	3198	Universal	TU2 – 1239/0302	January 2012
<b>Cobra</b>	8166/8	Universal	TU2 – 1102/0200	January 2012
<b>Cobra</b>	8808	VW models, Skoda models, Audi models, Mercedes models, Fiat models, BMW models <b>(Contact Vestatec for details)</b>	TU2 – 1309/1004	January 2012
<b>Code Alarm</b>	Miami	Universal	TU2 – 605/0897	11 Nov 1999
<b>Ford</b>	Ford 100 + Ford 300	Universal	TU1 – 363/1096	October 1998
<b>Foxguard</b>	FP – OP	Universal	TU1 – 320/0696	October 1998
<b>Gemel</b>	GR 470	Universal	TU2 – 703/0198	December 2006
<b>Gemel</b>	E247T	Universal	TU2 – 1350/0705	April 2008
<b>Gemini</b>	7350 U	Universal	TU2 – 1156/0400	November 2009
<b>GT Auto Alarm</b>	GT 108/142	Universal	TU2 – 1061/1098	June 2009
<b>GT Auto Alarm</b>	GT 908.2-1	Universal	TU2 – 1379/1106	July 2011
<b>Hamilton &amp; Palmer</b>	Black Box 2 → 1	Universal	TU2 – 1263/0802	January 2012
<b>Laserline</b>	993 V2	Universal	TU2 – 321/1098	11 Nov 1999
<b>Laserline</b>	290i	Universal	TU2 – 1086/0499	March 2004

<b>Meta</b>	M99T	Universal	TU1 – 285/1295	October 1998
<b>Meta</b>	M99T (Microwave)	Universal	TU2 – 1045/0898	April 2008
<b>Meta</b>	M99 T2	Universal	TU2 – 1044/0898	April 2008
<b>Scorpion</b>	918U	Universal	TU1 – 158/0296	October 1998
<b>Scorpion</b>	SA70	Universal	TU2 – 1374/1106	June 2009
<b>Scorpion</b>	SA80	Universal	TU2 – 1382/1106	June 2009
<b>Scorpion</b>	1015 T2	Universal	TU2 – 296/0898	August 2010
<b>Scorpion</b>	1215 T2	Universal	TU2 – 1070/0199	August 2010
<b>Secure Microsystems</b>	Sigma M34	Universal	TU2 – 805/0198	December 2006
<b>Secure Microsystems</b>	Sigma SG34	Universal	TU1 – 283/1295	October 1998
<b>Selca</b>	FC 6.71	Universal	TU2 – 1163/1100	December 2006
<b>Shurlok</b>	SK34	Universal	TU2 – 1151/0800	December 2006
<b>Texalarm</b>	AV 2950 GBT	Universal	TU1 – 346/0197	October 1998
<b>Texalarm</b>	2960	Universal	TU2 – 1057/1098	October 2007
<b>Texalarm</b>	2970	Universal	TU2 – 1058/1098	October 2007
<b>Texalarm</b>	2980	Universal	TU2 – 1205/0301	October 2007
<b>Toad</b>	A 221	Universal	TU2 – 400/0397	July 2004
<b>Toad</b>	Compact C4	Universal	TU2 – 1138/0100	August 2010
<b>Toad</b>	Maxpower MP4	Universal	TU2 – 1187/1100	August 2010
<b>Vecta</b>	2 – 1 Alarm	Universal	TU1 – 331/0696	October 1998
<b>Vecta</b>	The New CAT 2-1 upgrade	Universal	TU2 – 1090/0499	December 2006
<b>Virgin</b>	Virgin 2-1 Upgrade	Universal	TU2 – 1192/1200	August 2007
<b>Vision UK</b>	Aegis VAE 318-1820	Universal	TU2 – 1142/0200	August 2007

These systems should be recognised as normal compliant systems **if installed prior** to the date of deletion shown unless otherwise indicated. These systems may no longer be in production and may have been superseded by an updated system.

Please note the above statement is subject to individual insurer’s discretion.

## Category 2 → 1 (AFTERMARKET SYSTEMS – Malaysian Market)

### Alarm Upgrade

Company/ System	Evaluation No:	Feature Code	Fitment Policy
Daihatsu by Panasonic Electric Works Alarm System	TU2 – 1485/0611	R U L	Diahatsu Avanza

## THE LISTING OF SYSTEMS DELETED FROM LIST [AFTERMARKET – MALAYSIAN MARKET]

CAT 2 → 1				
Panasonic Electric Works	Alarm System	Daihatsu Avanza	TU2 – 1366/0906	June 2011

These systems should be recognised as normal compliant systems **if installed prior** to the date of deletion shown unless otherwise indicated. These systems may no longer be in production and may have been superseded by an updated system. Please note the above statement is subject to individual insurer’s discretion.

## Category 2 → 1

### [Utilising the original equipment remote tested to Issue 2 Criteria]

Company/System	Evaluation No	Feature Code	Applicable Vehicles
<b>Autowatch</b> 695 RLC CAN	TU3 – 1448/1108	R 2 U L	<b>For applicable vehicles with an approved remote. Please contact manufacturer for fitment compatibility.</b>
<b>Clifford</b> 330 X1/ X2/ X3	TU2 – 1432/0308	R U L	
<b>Cobra</b> 3868 (3865)	TU2 – 1256/0902	R U L	
<b>Cobra</b> 4405	TU3 – 1444/1208	R U L	
<b>Cobra</b> 4908	TU2 – 1362/0606	R U L	
<b>Cobra</b> 4615	TQA 260	R U L	
<b>Gemini</b> 7621T	TU2 – 1342/0705	R U L	
<b>Gemini</b> 931T	TU3 – 1447/1210	R U L	
<b>Laserline (S.p.A.)</b> 270 UK	TU2 – 1245/0302	R U/M L E O	
<b>Laserline (S.p.A.)</b> 278	TU2 – 1369/0506	R U/M L E O	
<b>Laserline (S.p.A.)</b> 670	TU2 – 1426/1207	R U/M L E O	
<b>*MED (S.p.A.)</b> 7450UK	TU3 – 1470/0310	R U L	
<b>Sigma</b> S32	TU2 – 1300/0204	R/K U L E O	<b>For applicable vehicles with an approved remote. Please contact manufacturer for fitment compatibility.</b>
<b>Sigma</b> S35	TU3 – 1479/0111	R U L	
<b>Vauxhall</b> Security System MVX2/3	TU2 – 1316/0304	R U L	<b>Vauxhall Models without CAN BUS</b>
			<b>For applicable vehicles with an approved remote Please contact manufacturer for fitment compatibility.</b>

\*See Landi Renzo S.p.A.

## THE LISTING OF SYSTEMS DELETED FROM LIST [AFTERMARKET]

CAT 2 → 1 (Utilising the original equipment remote tested to issue 2 Criteria)				
<b>Clifford</b>	330 X2	Model Specific	TU2 – 1433/0308	March 2010
<b>Clifford</b>	330 X3	Model Specific	TU2 – 1434/0308	March 2010
<b>Gemel</b>	E541	Model Specific	TU2 – 1292/0703	December 2006
<b>Gemel</b>	E252T	Model Specific	TU2 – 1348/0705	December 2010
<b>GT Auto Alarm</b>	GT908.2-1A	Model Specific	TU2 – 1380/1106	July 2011
<b>Meta</b>	M750T	Model Specific	TU2 – 1160/0301	December 2006
<b>Metasystems</b>	HPBT CAN	Model Specific	TU2 – 1402/0307	January 2010
<b>Metasystems</b>	HPBT/HPBT CAN	Model Specific	TU2 – 1306/0304	December 2010
<b>Scorpion</b>	SA40	Model Specific	TU2 – 1375/1106	December 2010
<b>Secure Microsystems</b>	M32	Model Specific	TU2 – 806/0198	December 2006
<b>Toad</b>	850T	Model Specific	TU2 – 1104/0799	August 2010
<b>Vauxhall</b>	Security System MVX3	Model Specific	TU2 – 1317/0404	January 2010
<b>Virgin</b>	Virgin 2-1 Upgrade Remote	Model Specific	TU2 – 1193/1200	August 2007

These systems should be recognised as normal compliant systems **if installed prior** to the date of deletion shown unless otherwise indicated. These systems may no longer be in production and may have been superseded by an updated system. Please note the above statement is subject to individual insurer's discretion.